Electric Fund Capital Outlay Requests Adopted Budget FY 2018-19

| | | | Regulatory | | New / | | Cost | | |
|--|-------------|------------|------------|--|-------------|-----|----------|---------|--|
| Fund | Cost Center | Account | Account | Description | Replacement | Qty | Per Unit | Total | Justification |
| 496 | PS12A | 15041_0000 | 10700 | Electric Cart | R-Replace | 2 | 15,000 | 30,000 | Cart 324 and 363 have reached the end of their useful life and need to be replaced |
| 496 | PS12A | 15041_0000 | 10700 | Thermal Imaging Camera | N-New | 1 | 35,000 | 35,000 | Tool to locate safety concerns, perform predictive maintenance and optimize equipment efficiency. |
| 496 | PS12A | 15041_0000 | 10700 | Electric cart | R-Replace | 1 | 12,000 | 12,000 | Cart 427 has reached end of useful life and needs to be replaced. |
| 496 | PS12E | 15041_0000 | 10700 | Chevy Bolt (all-electric vehicle) | R-Replace | 1 | 42,000 | 42,000 | Recommended by Fleet Manager - reliability is going down and the miles are high |
| 496 | PS31A | 15041_0000 | 10700 | Pickup Truck | R-Replace | 1 | 50,000 | 50,000 | Recommended by Fleet Manager because old truck is high maintenance parts obsolescence and reduced reliability. |
| 496 | PS31A | 15041_0000 | 10700 | Electric Forklift | R-Replace | 1 | 55,000 | 55,000 | Recommended by Fleet Manager because old forklift is high maintenance, parts obsolescence, reduced reliability and it doesn't meet air pollution level requirements. |
| 496 | PS31A | 15041_0000 | 10700 | Diesel particulate filters for crane truck | R-Replace | 1 | 20,000 | 20,000 | Recommended my Fleet Manager because 338 is in good condition but requires new diesel particulate filters to meet emission regulations. |
| 496 | PS31B | 15041_0000 | 10700 | Utility bed Pickup truck with lift gate, light bar and/or other options. Possibly Hybrid | R-Replace | 1 | 80,000 | 80,000 | Recommended by Fleet Manager due to age, high maintenance, parts obsolescence, and reduced reliability. Unit cost reflects safety lighting and utility bed configuration needed for the effective storage of tools and equipment required by crew to efficiently complete their assigned tasks. |
| 496 | PS31B | 15041_0000 | 10700 | Utility bed Pickup with lift gate, light bar and/or other options. Possibly Hybrid | R-Replace | 1 | 80,000 | 80,000 | Recommended by Fleet Manager due to age, high maintenance, parts obsolescence, and reduced reliability. Unit cost reflects safety lighting and utility bed configuration needed for the effective storage of tools and equipment required by crews to efficiently complete their assigned tasks. |
| 496 | PS31B | 15041_0000 | 10700 | Diesel Particulate Filter Installation | N-New | 1 | 20,000 | 20,000 | Recommended by Fleet Manager in case an existing fleet equipment becomes subject to a mandated SCAQMD upgrade. |
| 496 | PS31B | 15041_0000 | 10700 | AQMD approved Replacement power unit for existing cable cart | R-Replace | 1 | 10,000 | 10,000 | Intent is to replace the power unit with an SCAQMD approved engine. The funds (\$80,000) allocated for this in the FY17-18 budget may be insufficient. |
| 496 | PS31E | 15041_0000 | 10700 | OH Distribution Transformers | N-New | 1 | 400,000 | 400,000 | Overhead distribution transformer orders |
| 496 | PS31E | 15041_0000 | 10700 | UG Distribution Transformers | N-New | 1 | 400,000 | 400,000 | Underground distribution transformer orders |
| 496 | PS31T | 15041_0000 | 10700 | Pickup Truck | R-Replace | 1 | 50,000 | 50,000 | Recommended by Fleet Manager because old truck is high maintenance parts obsolescence and reduced reliability. |
| 496 | PS31T | 15041_0000 | 10700 | Cordless 3 phase Transformer Ratio (TTR) Tester. | N-New | 1 | 17,000 | 17,000 | Cordless 3 phase transformer turns ratio tester will increase field testing efficiencies. |
| 496 | PS42S | 15041_0000 | 10700 | Ford 150 | R-Replace | 1 | 39,375 | 39,375 | Recommended by Fleet Manager - truck is old & requires high maintenance |
| 496 | PS42S | 15041_0000 | 10700 | Ford 150 | R-Replace | 1 | 39,375 | 39,375 | Recommended by Fleet Manager - truck is old & requires high maintenance |
| 496 | PS45A | 15041_0000 | 10700 | 4 door car | R-Replace | 1 | 37,170 | 37,170 | Recommended replacement by fleet manager due to anticipated high maintenance cost |
| 496 | PS45A | 15041_0000 | 10700 | BWP Corporate Server Replacement | R-Replace | 1 | 39,825 | 39,825 | Replace BWP corporate servers End of Life |
| TOTAL ELECTRIC FUND CAPITAL OUTLAY REQUESTS \$ 1,456,745 | | | | | | | | | |