Capital Outlay Requests Adopted Budget FY2021-22

			Regulatory		New /		Cost		
Fund	Cost Center	Account	Account	Description	Replacement	Qty	Per Unit	Total	Justification
497	PS51A	15041_0000	10500	2007 Construction Backhoe	R-Replace	1	175,000	,	Replace due to condition and diesel engine regulatory compliance
497	PS51A	15041_0000	10500	20"-40" Inflatable Pipe Plugs	N-New	2	3,750	7,500	Water isolation for large valve repair/replacement
497	PS51A	15041_0000	10500	Mueller Air Operator for Mueller Company	R-Replace	1	8,100	8,100	Replace due to condition
497	PS51B	15041_0000	10500	Online Chlorine Residual Analyzer	R-Replace	2	6,500		Existing analyzers are not as accurate or reliable due to age and continuous use.
497	PS51B	15041_0000	10500	Multi Parameter Water Test Equipment	N-New	1	5,500		Multi parameter water test equipment needed for mandated water quality sampling analysis.
497	PS51B	15041_0000	10500	Online Analyzer for Water Disinfection Free Ammonia, Temperature, and Monochloramine	N-New	1	25,000	25,000	Online analysis of important disinfection parameters
497	PS51D	15041_0000	10500	PI Enterprise License	N-New	1	100,000	,	The OSIsoft PI Enterprise License will address the current limitations to server, data, training and support that is neede for operational and historical data needs and goals.
497	PS51D	15041_0000	10500	Taylor Dunn Electric Cart	R-Replace	1	1,725	1,725	Replace due to age, reliability, and condition
497	PS51D	15041_0000	10500	Server Hardware Replacement	R-Replace	2	12,800	25,600	Replace due to age, support, and end of life
497	PS51D	15041_0000	10500	Taylor Dunn Electric Cart	R-Replace	1	1,725	1,725	Replace due to age, reliability, and condition

GRAND TOTAL WATER FUND CAPITAL OUTLAY REQUESTS

\$ 363,150 .